

ISCO 730 MODULE SOFTWARE HISTORY

REVISION 1.07

Software Release Date: 11/1/95

Corrections: Fixed a bug that periodically caused the air pump to cycle twice for one air pressure event.

Enhancements:

- 1- Release version of software for the 10' bubbler module.
- 2- Checks for hardware compatibility.

REVISION 1.03

Software Release Date: 2/14/95

Corrections: Revised calibration procedures.

Enhancements: None.